

## Kurnell Update – 14 June 2022

<u>Key activities:</u> Replacement of embankment along Solander Street is progressing and so is the remedial works in the carpark of the Rec Club. Works on the access path to the Girl Guide Hall has continued.

Remediation	Location description	Work completed
Zone		·
1	Area north of Torres St/Captain Cook Drive roundabout	Remediation of the road verge has now been completed. Additional remediation work has now been completed to remove remaining contamination. Validation results show that remediation was successful and is now completed. Remaining works include replacement works of driveways in private properties. These works are being coordinated with
		individual residents.
2	Impacted area near horse arena	Remediation of gross contamination has been completed. Validation results from this zone have been published, showing that remediation was successful.
3 West	Area southwest of Torres St / Captain Cook Drive roundabout	Remediation has been completed. Validation results from this zone have been published, showing that remediation was successful.
3 East	Area southeast of Torres St / Captain Cook Drive roundabout	Additional remediation work has been completed to remove remaining contamination.  Validation results of this one location show that remediation was successful.
4 East	East side of Captain Cook Drive between Torres and Solander Streets.	Additional remediation work has been completed to remove remaining contamination. Validation results show that the remediation was successful and is now completed.  Additional works include the access ramp to the Girl Guide Hall and the reinstatement of the embankment and railing along a section on the northern side of Solander Street.
4 West	West side of Captain Cook Drive between Bridges and Torres Streets	Additional remediation work has been completed to remove remaining contamination. Validation results of these two locations show that remediation was successful.
5	Area behind Girl Guides Hall	Remediation has been completed. Validation results from this zone have been published, showing that remediation was successful.
6	Western side of Captain Cook Drive south of Bridges Street	Remediation has been completed. Validation results from this zone have been published. Apart from two locations, remediation was successful.  The remaining impacted soil in one of these 2 locations has been removed. Validation results of this one location show that remediation was successful.  Since the second location is among tree roots, a monitoring plan will be implemented involving an arborist. There are no risks from small amounts of remaining contaminants identified since the impacted soil is already covered with clean soil and fresh grass. Remaining works include the development of a management plan for the remaining contamination that cannot be removed without causing further impact.
7	Area in front of Rec Club and southern side of Solander Street	Remediation of the road verges has been completed. Validation results from 60% of this zone show that remediation was successful apart from two locations, The impacted soils at these two locations have been removed. Awaiting validation results. Remediation and grass replacement works will continue into the carpark of the Rec Club.
8	Impacted private property	Remediation of gross contamination has been completed. Validation results show remediation was successful.

Waterways	Cleaning up in waterways is continuing.	
Other updates	See <a href="https://www.ampol.com.au/about-ampol/news-and-media/kurnell-update">https://www.ampol.com.au/about-ampol/news-and-media/kurnell-update</a> - for further	
	updates.	
Contact Ampol	Ampol Community Hotline 1800 719 669 or Community@ampol.com.au	