

Over the weekend of 30 April and 1 May no excavation works will occur along Captain Cook Drive. This is to ensure community sport at Marton Park – Kurnell Stingrays – can occur with minimal disruption to traffic and to ensure parking space is available. Works over the weekend will be limited to the maintenance of fresh grass areas and the continued monitoring of wetlands with booms replaced as required. Please call our community line with any questions or concerns.

Remediation Zone	Location description	Work completed
1	Area north of Torres St/Captain Cook Drive roundabout	Public areas are remediated and covered with turf. Awaiting validation sampling results. We have been in discussions with adjacent residents and Council to progress driveway works. Quality review of the works identified the need for additional soil and improvement of grass coverage. This work is ongoing.
2	Impacted area near horse arena	Remediated and covered with turf. Soil results have been received from the lab validating the completion of the remediation works. Results have been shared with EPA and Council. Council have re-opened the Horse Arena. Ampol will continued to look after the fresh turf.
3 West	Area southwest of Torres St / Captain Cook Drive roundabout	Remediated and covered with turf. Awaiting validation of resampling results.
3 East	Area southeast of Torres St / Captain Cook Drive roundabout.	Remediation continuing in southerly direction. Validation samples have been taken and clean soil has been put back. Area is awaiting to be covered with new turf.
4 East	Captain Cook Drive, remaining impacted areas.	Remediation works continuing in southerly direction.
4 West	Captain Cook Drive, remaining impacted areas.	Test pitting was completed. Plans have been developed to start implementation on Monday.
5	Impacted area near Girl guide hall areas.	Remediated and covered with turf. Awaiting validation of resampling results. Continued to maintain and water area.
6	Captain Cook Drive, remaining impacted areas.	Remediation works continuing in southerly direction.
7	Captain Cook Drive, remaining impacted areas.	Works have not yet commenced in this area.
8	Impacted private property	Working with owners to finalise start date.
Clean-up works		
Waterways		Clean up in waterways is continuing: 10 booms are in place with daily inspection and removal of material collected behind booms where required. Material collected currently is general biological/natural material
Other updates	See https://www.ampol.com.au/about-ampol/news-and-media/kurnell-update - for further updates	
Contact Ampol	Kurnell site office 1800 802 385 ampolfeedback@ampol.com.au	