

Kurnell Update - 2 May 2022

On Saturday morning it was observed that a large diseased tree had fallen across the jogging path into the children's play area behind Marton Hall. The area was cordoned off and the tree was moved to the side to make the area safe. In addition, the play area was cleared of debris created.

| Remediation | Location description | Work completed |
|---------------|--|---|
| Zone | P. C. | |
| 1 | Area north of Torres St/Captain Cook Drive roundabout | Watering of newly installed grass. |
| 2 | Impacted area near horse arena | Remediation complete. Watering of newly installed grass. |
| 3 West | Area southwest of Torres St / Captain Cook Drive roundabout | Remediated and covered with turf. Await validation resampling results. Watering of newly installed grass. |
| 3 East | Area southeast of Torres St / Captain Cook Drive roundabout | Watering of newly installed grass. Vacuum truck booked to commence non-destructive excavation due to number of services and the required depth. |
| 4 East | East side of Captain Cook Drive between Bridges and Torres Streets | Remediation conducted up to the corner of Solander Street. Some small patches to be completed on eastern side of the timber gate. |
| 4 West | West side of Captain Cook Drive between Bridges and Torres Streets | One work crew heading south from roundabout. Two work fronts in zone 4 west. Planning for second work crew to commence excavation in Zone 4 West at footpath bend. Work crew to continue to meet up with work crew at northern end of zone 4 west. Planning to engage businesses to coordinate when work will/can commence in areas around entry and exit of business on corner Bridges Street and Captain Cook Drive |
| 5 | Area behind Girl Guides Hall | Remediation complete. Watering of newly installed grass. |
| 6 | Western side of Captain Cook Drive south of Bridges Street | Work crew continuing in a southerly direction towards creek opposite vacant lot |
| 7 | Area in front of Rec Club and southern side of Solander Street | Works have not yet commenced in this area. |
| 8 | Impacted private property | Works have not yet commenced in this area. Awaiting approval. |
| Clean-up | | |
| Waterways | | Cleaning up in waterways is continuing |
| Other updates | See https://www.ampol.com.au/about-ampol/news-and-media/kurnell-update - for further updates. Testing results for Marton Park and horse area will be made available tomorrow. | |
| Contact Ampol | Kurnell site office 1800 802 385 ampolfeedback@ampol.com.au | |