

Kurnell Update - 4 May 2022

Works progressing well. Planned work from tomorrow through to Saturday, around the entry and exit driveways at the Kurnell village shops. Traffic control personnel will be stationed throughout work for pedestrian and vehicle access. Vehicle access to carpark in front of the shops will be open with minor delays expected.

Remediation Zone	Location description	Work completed
1	Area north of Torres St/Captain Cook Drive roundabout	Remediation complete excluding driveways and private residents. Awaiting validation results from remediation sections. Watering of newly installed grass.
2	Impacted area near horse arena	Remediation 100% complete. Area has been reopened Validation results have been received. Watering of newly installed grass.
3 West	Area southwest of Torres St / Captain Cook Drive roundabout	Remediated and covered with turf. Await validation resampling results. Watering of newly installed grass.
3 East	Area southeast of Torres St / Captain Cook Drive roundabout	Watering of newly installed grass of remediated section. ~25% of the zone has been remediated. Awaiting validation results of that section. Service provider engaged and Ampol awaiting advice for intricate remediation works in remaining area.
4 East	East side of Captain Cook Drive between Bridges and Torres Streets	~ 70% of the zone has been remediated. Awaiting validation results of that section. Watering of newly installed grass.
4 West	West side of Captain Cook Drive between Bridges and Torres Streets	Crew working south along footpath area. Impacted area of the park around 'the meeting place' sign has been remediated and replaced with clean soil. Plants and wood chips are being sourced to be reinstated. ~30% of the Zone has been remediated. Awaiting validation results. Watering of newly installed grass.
5	Area behind Girl Guides Hall	Remediation complete in the central section of this Zone. Awaiting validation results. Watering of newly installed grass. Some additional works are required east of the hall
6	Western side of Captain Cook Drive south of Bridges Street	Work crew continuing in a southerly direction towards creek. ~70% of the Zone has been remediated. Awaiting validation results of that section. Watering of newly installed grass.
7	Area in front of Rec Club and southern side of Solander Street	Works have not yet commenced in this area.
8	Impacted private property	Works have not yet commenced in this area. Awaiting owners' approval.
Clean-up		
Waterways		Cleaning up in waterways is continuing.
Other updates	See https://www.ampol.com.au/about-ampol/news-and-media/kurnell-update - for further updates	
Contact Ampol	PLEASE NOTE NEW PHONE NUMBER AND EMAIL ADDRESS Ampol Community Hotline 1800 719 669 Community@ampol.com.au	