Kurnell Update - 26 May 2022



<u>Key activities:</u> Remediating Council Park area has continued, Zone 7 grass replacement works continuing and northern footpath of Solander Street is progressing, leveling of soil and re-laying of turf in Zone 1.

Remediation	Location description	Work completed
Zone		Tronk completes
1	Area north of Torres St/Captain Cook Drive roundabout	~75% of area has been remediated. This includes the grassed areas in the road verge. Validation results from remediated sections have been published. Apart from one location, remediation was successful. The remaining impacted soil in this one location will be removed once the initial scope of the remediation has been completed. There are no risks from small amounts of remaining contaminants identified since the impacted soil is already covered with clean soil and fresh grass. Watering of newly installed grass. Remediation works of driveways and in private properties (remaining 25%) is being coordinated with individual residents.
2	Impacted area near horse arena	Remediation 100% complete. Area has been reopened. Validation results have been published, showing that remediation was successful. Watering of newly installed grass continuing.
3 West	Area southwest of Torres St / Captain Cook Drive roundabout	Remediation 100% complete. Validation results from this zone have been published, showing that remediation was successful. Watering of newly installed grass continuing.
3 East	Area southeast of Torres St / Captain Cook Drive roundabout	~85% of zone remediated. Validation results from remediated sections have been published. Apart from one location, remediation was successful. The remaining impacted soil in this one location will be removed once the initial scope of the remediation has been completed. There are no risks from small amounts of remaining contaminants identified since the impacted soil is already covered with clean soil and fresh grass. Remediation of the remaining 20% area has been completed and awaiting results from validation samples. Watering of newly installed grass continuing.
4 East	East side of Captain Cook Drive between Torres and Solander Streets. West side of Captain Cook	~82% of the zone remediated. Validation results from remediated sections have been published, showing that remediation was successful. Watering of newly installed grass and garden continuing. The driveways at Men's Shed and Girl Guides Hall have been poured including the laybacks. Council requirements stipulate that a 7-day curing period is maintained. Remediating along northern footpath of Solander Street is progressing. ~78% of zone remediated.
	Drive between Bridges and Torres Streets	Awaiting validation results. Progressing the remediation in the council park area. Watering of newly installed grass and gardens continuing.
5	Area behind Girl Guides Hall	Remediation completed of central section of this Zone. Validation results from remediated area have been published, showing that remediation was successful. Watering of newly installed grass and garden continuing.
6	Western side of Captain Cook Drive south of Bridges Street	~80% of zone remediated. Validation results from remediated sections have been published. Apart from one location, remediation was successful. The remaining impacted soil in this one location will be removed once the initial scope of the remediation has been completed. There are no risks from small amounts of remaining contaminants

		identified since the impacted soil is already covered with clean soil and fresh grass. Watering of newly installed grass continuing.	
7	Area in front of Rec Club and southern side of Solander Street	~20% of zone remediated. Remediation and grass replacement works continuing.	
8	Impacted private property	~45% progress of remediation work. Validation results show that excavation can be filled in and grass will be re-established in the coming week. Front area has been re-established.	
Clean-up			
Waterways		Cleaning up in waterways is continuing.	
Other updates	See https://www.ampol.com.au/about-ampol/news-and-media/kurnell-update - for further updates. Additional personnel have been included at the work fronts to further improve overall safety.		
Contact Ampol	Ampol Community Hotline 1800 719 669 or Community@ampol.com.au		