


Ampol Kurnell Terminal – Flooding Incident

**Figure 1.5**Remediation Zone5 Validation sampling

**Emergency Response** 

## Legend

- Remediation Zone Samples
- Remediation Zone 5



Coordinate system: GDA2020 MGA Zone

Scale ratio correct when printed at A1

1:75 Date: 9/05/2022

Date of imagery: 22/03/2022

Data sources: - DNRME, TMR, Translink, Geoscience Australia

© WSP Australia Pty Ltd ("WSP") Copyright in the drawings, information and data recorded ("the information") is the property of WSP. This document and the information are solely for the use of it authorised recipient and this document may not be used, opped or reproduced in whole or part for any purpose other than that which it was supplied by WSP. WSP makes no representation, undertakes no duty and accepts no responsibility to any third party who may use or rely upon this document or the information. NSS Certified Quality System to ISO 901.0 A PSPROVED FOR AN