

Works progressing well, focusing along western side of Captain Cook Drive. Remediation works on Saturday, along Bridges Street at the Kurnell village shops. Traffic control personnel will be stationed during the works to direct pedestrian and vehicle access. Vehicle access to carpark in front of the shops will remain open with minor delays expected. Revisiting Zone 5 area behind Girl Guide Hall on Saturday to improve grassed area.

Remediation Zone	Location description	Work completed
1	Area north of Torres St/Captain Cook Drive roundabout	~75% of the area has been remediated. This includes the grassed areas in the road verge. Awaiting validation results from remediation sections. Watering of newly installed grass. Remediation works of driveways and in private properties (remaining 25%) is being organised with the individual residents directly.
2	Impacted area near horse arena	Remediation 100% complete. Area has been reopened. Validation results published. Watering of newly installed grass.
3 West	Area southwest of Torres St / Captain Cook Drive roundabout	Remediated and covered with turf. Awaiting validation resampling results. Watering of newly installed grass.
3 East	Area southeast of Torres St / Captain Cook Drive roundabout	Watering of newly installed grass of remediated section. ~25% of the zone has been remediated. Awaiting validation results. Service providers (Telstra, NBN) are engaged and Ampol awaiting advice for intricate remediation works in remaining area.
4 East	East side of Captain Cook Drive between Bridges and Torres Streets	~70% of the zone has been remediated. Awaiting validation results of that section. Continuing work in isolated pockets in front of Girl Guide Hall and behind the wooden fence. Watering of newly installed grass.
4 West	West side of Captain Cook Drive between Bridges and Torres Streets	Crew working south along footpath in front of “the meeting place” area. Area in front of Kurnell village shops has been remediated. ~50% of the Zone has been remediated. Awaiting validation results. Watering of newly installed grass.
5	Area behind Girl Guides Hall	Remediation completed in central section. Awaiting validation results of that section. Watering of newly installed grass. Some additional works are required east of the hall
6	Western side of Captain Cook Drive south of Bridges Street	Work crew continuing along creek around foot bridge. ~75% of the Zone has been remediated. Awaiting validation results of that section. Watering of newly installed grass.
7	Area in front of Rec Club and southern side of Solander Street	Works have not yet commenced in this area.
8	Impacted private property	Works have not yet commenced in this area. Awaiting owners’ approval.
Clean-up		
Waterways		Cleaning up in waterways is continuing.
Other updates	See https://www.ampol.com.au/about-ampol/news-and-media/kurnell-update - for further updates	
Contact Ampol	PLEASE NOTE NEW PHONE NUMBER AND EMAIL ADDRESS Ampol Community Hotline 1800 719 669 Community@ampol.com.au	