

Key activities: Replacement of embankment along Solander Street is progressing and so is the remedial works in the carpark of the Rec Club. Final landscaping being completed at the access path to the Girl Guide Hall.

| Remediation Zone | Location description | Work completed |
|------------------|--|---|
| 1 | Area north of Torres St/Captain Cook Drive roundabout | Remediation of the road verge has been completed. Additional remediation work has now been completed to remove remaining contamination. Validation results show that remediation was successful and is now completed. Remaining works include replacement works of driveways in private properties. These works are being coordinated with individual residents. |
| 2 | Impacted area near horse arena | Remediation has been completed. Validation results from this zone have been published, showing that remediation was successful. |
| 3 West | Area southwest of Torres St / Captain Cook Drive roundabout | Remediation of has been completed. Validation results from this zone have been published, showing that remediation was successful. |
| 3 East | Area southeast of Torres St / Captain Cook Drive roundabout | Additional remediation work has now been completed to remove remaining contamination. Validation results show that remediation was successful and is now completed. |
| 4 East | East side of Captain Cook Drive between Torres and Solander Streets. | Additional remediation work has now been completed to remove remaining contamination. Validation results show that remediation was successful and is now completed. Additional works also include the access ramp to the Girl Guide Hall and the reinstatement of the embankment and railing along a section on the northern side of Solander Street. |
| 4 West | West side of Captain Cook Drive between Bridges and Torres Streets | Additional remediation work has now been completed to remove remaining contamination. Validation results show that remediation was successful and is now completed |
| 5 | Area behind Girl Guides Hall | Remediation has been completed. Validation results from this zone have been published, showing that remediation was successful. |
| 6 | Western side of Captain Cook Drive south of Bridges Street | Remediation has been completed. Validation results from this zone have been published. Apart from two locations, remediation was successful. The remaining impacted soil in one of these two locations has been removed. Validation results of this one location show that remediation was successful. Since the second location is among tree roots, a monitoring plan will be implemented involving an arborist. There are no risks from small amounts of remaining contaminants identified since the impacted soil is already covered with clean soil and fresh grass. Remaining works include the development of a management plan for the remaining contamination that cannot be removed without causing further impact. |
| 7 | Area in front of Rec Club and southern side of Solander Street | Remediation of the road verges has been completed. Validation results from 60% of this zone show that remediation was successful apart from two locations. Additional remediation work has now been completed to remove remaining contamination. Validation results show that remediation was successful. Remediation and grass replacement works will continue into the carpark of the Rec Club. |
| 8 | Impacted private property | Remediation has been completed. Validation results show remediation was successful. |

| | | |
|----------------------|--|---|
| Clean-up | | |
| Waterways | | Cleaning up in waterways is continuing. Long-term ecological study of the wetlands has commenced this week. |
| Other updates | See https://www.ampol.com.au/about-ampol/news-and-media/kurnell-update - for further updates. | |
| Contact Ampol | Ampol Community Hotline 1800 719 669 or Community@ampol.com.au | |