

Remediating areas at Girl Guides Hall, along the path at ‘the meeting place’ and progressing along the corner of Bridges Street and Captain Cook Drive.

Remediation Zone	Location description	Work completed
1	Area north of Torres St/Captain Cook Drive roundabout	Approximately 75% of area has been remediated. This includes the grassed areas in the road verge. Validation results from remediated sections have been published. Remediation was successful with exception of one location, which showed an increased level of Benzo(a)Pyrene. The remaining impacted soil in this location will be removed in the coming weeks. Watering of newly installed grass. Remediation works of driveways and in private properties (remaining 25%) is being coordinated with individual residents.
2	Impacted area near horse arena	Remediation 100% complete. Area has been reopened. Validation results have been published. Watering of newly installed grass continuing.
3 West	Area southwest of Torres St / Captain Cook Drive roundabout	Remediation 100% complete. Validation results from this zone have been published, showing that remediation was successful. Watering of newly installed grass continuing.
3 East	Area southeast of Torres St / Captain Cook Drive roundabout	Approximately 80% of zone remediated. Validation results from remediated sections have been published. Remediation was successful with exception of one location, which showed an increased level of Benzo(a)Pyrene. The remaining impacted soil in this location will be removed in the coming weeks. Watering of newly installed grass continuing.
4 East	East side of Captain Cook Drive between Bridges and Torres Streets	Approximately 75% of the zone remediated. Validation results from remediated sections have been published, showing that remediation was successful. Watering of newly installed grass and garden continuing. The garden and lawn at the guide hall have been remediated.
4 West	West side of Captain Cook Drive between Bridges and Torres Streets	~72% of zone remediated. Awaiting validation results. Watering of newly installed grass and gardens continuing.
5	Area behind Girl Guides Hall	Remediation completed of central section of this Zone. Validation results from remediated area has been published, showing that remediation was successful. Watering of newly installed grass continuing.
6	Western side of Captain Cook Drive south of Bridges Street	~80% of zone remediated. Validation results from remediated sections have been published. Remediation was successful with exception of one location, which showed an increased level of Benzo(a)Pyrene. The remaining impacted soil in this location will be removed in the coming weeks. Watering of newly installed grass continuing.
7	Area in front of Rec Club and southern side of Solander Street	Works have not yet commenced in this area.
8	Impacted private property	~10% progress of remediation work. Awaiting validation results prior to reinstating.

Clean-up

Waterways	Cleaning up in waterways is continuing.
Other updates	See https://www.ampol.com.au/about-ampol/news-and-media/kurnell-update - for further update
Contact Ampol	Ampol Community Hotline 1800 719 669 Community@ampol.com.au