

Key activities: Remediating adjacent to Girl Guides Hall, Council strip along private property and progressing corner of Captain Cook Drive and Solander Street.

Remediation Zone	Location description	Work completed
1	Area north of Torres St/Captain Cook Drive roundabout	~75% of area has been remediated. This includes the grassed areas in the road verge. Validation results from remediated sections have been published. Apart from one location, remediation was successful. The remaining impacted soil in this location will be removed in the coming weeks. Watering of newly installed grass. Remediation works of driveways and in private properties (remaining 25%) is being coordinated with individual residents.
2	Impacted area near horse arena	Remediation 100% complete. Area has been reopened. Validation results have been published. Watering of newly installed grass continuing.
3 West	Area southwest of Torres St / Captain Cook Drive roundabout	Remediation 100% complete. Validation results from this zone have been published, showing that remediation was successful. Watering of newly installed grass continuing.
3 East	Area southeast of Torres St / Captain Cook Drive roundabout	~80% of zone remediated. Validation results from remediated sections have been published. Apart from one location, remediation was successful. The remaining impacted soil in this location will be removed in the coming weeks. Remediation of the remaining 20% area has progressed and awaiting results from validation samples. Watering of newly installed grass continuing.
4 East	East side of Captain Cook Drive between Torres and Solander Streets.	~77% of the zone remediated. Validation results from remediated sections have been published, showing that remediation was successful. Watering of newly installed grass and garden continuing. The driveways at Men's Shed and Girl Guides Hall have been excavated and samples taken. Awaiting validation results before progressing with the driveways. Remediating adjacent Girl Guides Hall and progressing corner of Captain Cook Drive and Solander Street.
4 West	West side of Captain Cook Drive between Bridges and Torres Streets	~73% of zone remediated. Awaiting validation results. Progress is made in remediating road verge of Bridges Street and awaiting the validation results from this area. Watering of newly installed grass and gardens continuing.
5	Area behind Girl Guides Hall	Remediation completed of central section of this Zone. Validation results from remediated area has been published, showing that remediation was successful. Watering of newly installed grass continuing.
6	Western side of Captain Cook Drive south of Bridges Street	~80% of zone remediated. Validation results from remediated sections have been published. Apart from one location, remediation was successful. The remaining impacted soil in this location will be removed in the coming weeks. Watering of newly installed grass continuing.
7	Area in front of Rec Club and southern side of Solander Street	Works have not yet commenced in this area.

8	Impacted private property	~18% progress of remediation work. Awaiting validation results prior to reinstating.
Clean-up		
Waterways		Cleaning up in waterways is continuing.
Other updates	See https://www.ampol.com.au/about-ampol/news-and-media/kurnell-update - for further updates. Following the completion of the remediation in the Horse Arena, the area has also been tidied up. Collected general waste will be removed in the coming days. Ampol has agreed to install an access ramp into the Girl Guide Hall. Discussions with Sutherland Shire Council have commenced.	
Contact Ampol	Ampol Community Hotline 1800 719 669 or Community@ampol.com.au	